



図 1





3/7

図 3

PC材  
 $B_m=0.2T$   
 $f=8Hz$




図 4

PC材  
 $B_m=0.2T$   
 $f=8Hz$





图 5



5/7

図 6

PC材  
 $B_m=0.65T$   
 $f=50Hz$





図 7

PC材  
 $B_m=0.65T$   
 $f=50Hz$



6/7

図 8

PB材  
 $B_m=0.9T$   
 $f=50Hz$




図 9

PD材  
 $B_m=0.9T$   
 $f=50Hz$




図 10

PC材  
 $B_m=0.65T$   
 $f=100Hz$

